ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli

Street ID	Street Name	Significant Landmark
W0319, W0339, W0250, W0317, W0321, W0268, W0313	11th Crs Lakshmi Sagar Lyt, NA	gangamma temple to kodigehalli

Segment No.	Total Length (m)
8/C-W0319/S083153	150.47

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	139.04	77.576863	13.058035	77.578096	13.058069	W0303	W0268
2	11.43	77.577097	13.057930	77.577135	13.058026	W0339	W0250

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Estimate for the Improvements to roads and drain from gangamma temple to kodigehalli main road in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yel	1500000	2013

Year	Type of Work	Other Work Type
2013 - 2014	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Estimate for the Improvements to roads and drain from gangamma temple to kodigehalli main road in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-14-000016

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-TND/WO/541/2013-14	28/02/2014	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
28/02/2014	27/02/2015	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N VENU		0.00

Phone No.	E-Mail ID
9448334159	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SRINIVASA MURTHY
Date of Inspection	**Remarks**	
24/11/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	8	Ward Name:	Kodigehalli	Street ID:	W0319, W0339, W0250, W0317,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/11/2016	24/12/2016	COMPLETED
SE	VASU K M	24/11/2016	24/12/2016	COMPLETED
EE	YARAPPA REDDY	24/11/2016	24/12/2016	COMPLETED
AEE	RAJINIKANTH MALLI	24/11/2016	24/12/2016	COMPLETED
AE	SRINIVAS MURTHY	24/11/2016	24/12/2016	COMPLETED
AE	SRINIVAS MURTHY	24/11/2016	24/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0319, W0339, W0250, W0317,